## **Document:** Errata, **Register Page Number:** 28 IR 1696

Source: March 1, 2005, Indiana Register, Volume 28, Number 6

**Disclaimer:** This document was created from the files used to produce the official CD-ROM Indiana Register.

## TITLE 675 FIRE PREVENTION AND BUILDING SAFETY COMMISSION

LSA Document #02-118(AC)

Under IC 4-22-2-38, corrects the following typographical, clerical, or spelling errors in LSA Document #02-118(F), printed at 26 IR 3032:

- (1) In 675 IAC 25-1-3(a), on page 3 of the original document (26 IR 3034), change the first sentence to read "Change the following definitions in Chapter 2 to read as follows:".
- (2) In 675 IAC 25-1-3(b), on page 3 of the original document (26 IR 3034), change the first sentence to read "Add the following definitions in Chapter 2 to read as follows:".
- (3) In 675 IAC 25-1-3(b), on page 3 of the original document (26 IR 3034), delete "INDIANA FULES GAS CODE (675 IAC 25)" and insert "INDIANA FUEL GAS CODE (675 IAC 25)".
- (4) In 675 IAC 25-1-3(b), on page 4 of the original document (26 IR 3034), delete "INDIANA PLUMBING CODE (675 16)" and insert "INDIANA PLUMBING CODE (675 IAC 16)".

Filed with Secretary of State: September 17, 2004, 2:28 p.m.

*Under IC 4-22-2-38(g)(2), this correction takes effect 45 days from the date and time filed with the Secretary of State.*