

**Document:** Final Rule, **Register Page Number:** 29 IR 12  
**Source:** October 1, 2005, Indiana Register, Volume 29, Number 1  
**Disclaimer:** This document was created from the files used to produce the official CD-ROM Indiana Register.

**TITLE 675 FIRE PREVENTION AND BUILDING  
SAFETY COMMISSION**

LSA Document #04-218(F)

DIGEST

Amends 675 IAC 25-1, the 2003 Indiana Fuel Gas Code, to make numerous substantive and clarifying changes. Effective 30 days after filing with the Secretary of State.

<b>675 IAC 25-1-7.2</b>	<b>675 IAC 25-1-9.3</b>
<b>675 IAC 25-1-7.4</b>	<b>675 IAC 25-1-9.5</b>
<b>675 IAC 25-1-7.6</b>	<b>675 IAC 25-1-9.7</b>
<b>675 IAC 25-1-9.1</b>	<b>675 IAC 25-1-9.9</b>

SECTION 1. 675 IAC 25-1-7.2 IS ADDED TO READ AS FOLLOWS:

**675 IAC 25-1-7.2 Table 308.2**

**Authority:** IC 22-13-2-2; IC 22-13-2-13

**Affected:** IC 22-12; IC 22-13; IC 22-14; IC 22-15; IC 36-7

**Sec. 7.2. In Table 308.2, delete “0.024” and insert “0.024 inch (24 gage)” in the left column in item numbers 3, 5, 7, and 8.** *(Fire Prevention and Building Safety Commission; 675 IAC 25-1-7.2; filed Aug 29, 2005, 9:45 a.m.: 29 IR 12)*

SECTION 2. 675 IAC 25-1-7.4 IS ADDED TO READ AS FOLLOWS:

**675 IAC 25-1-7.4 Figure 308.2(3)**

**Authority:** IC 22-13-2-2; IC 22-13-2-13

**Affected:** IC 22-12; IC 22-13; IC 22-14; IC 22-15; IC 36-7

**Sec. 7.4. Change the title of Figure 308.2(3) to read: “Masonry clearance reduction system”.** *(Fire Prevention and Building Safety Commission; 675 IAC 25-1-7.4; filed Aug 29, 2005, 9:45 a.m.: 29 IR 12)*

SECTION 3. 675 IAC 25-1-7.6 IS ADDED TO READ AS FOLLOWS:

**675 IAC 25-1-7.6 Section 403.11; plastic piping, joints, and fittings**

**Authority:** IC 22-13-2-2; IC 22-13-2-13

**Affected:** IC 22-12; IC 22-13; IC 22-14; IC 22-15; IC 36-7

**Sec. 7.6. In Section 403.11, Plastic piping, joints and fittings, change the third sentence in item number 3 to read: “The stiffener shall be flush with the end of the pipe or tubing and shall extend at least to the outside end of the compression fitting when installed.”.** *(Fire Prevention and Building Safety Commission; 675 IAC 25-1-7.6; filed Aug 29, 2005, 9:45 a.m.: 29 IR 12)*

SECTION 4. 675 IAC 25-1-9.1 IS ADDED TO READ AS FOLLOWS:

**675 IAC 25-1-9.1 Section 503.5.3; masonry chimneys**

**Authority:** IC 22-13-2-2; IC 22-13-2-13

**Affected:** IC 22-12; IC 22-13; IC 22-14; IC 22-15; IC 36-7

**Sec. 9.1. In Section 503.5.3, masonry chimneys, change, in the last sentence (after exception), the referenced section number to 503.6.5.** *(Fire Prevention and Building Safety Commission; 675 IAC 25-1-9.1; filed Aug 29, 2005, 9:45 a.m.: 29 IR 12)*

SECTION 5. 675 IAC 25-1-9.3 IS ADDED TO READ AS FOLLOWS:

**675 IAC 25-1-9.3 Table/Figure 503.6.6**

**Authority:** IC 22-13-2-2; IC 22-13-2-13

**Affected:** IC 22-12; IC 22-13; IC 22-14; IC 22-15; IC 36-7

**Sec. 9.3. In the second row of Table/Figure 503.6.6, before 6/12 to 7/12, insert “over”.** (*Fire Prevention and Building Safety Commission; 675 IAC 25-1-9.3; filed Aug 29, 2005, 9:45 a.m.: 29 IR 12*)

SECTION 6. 675 IAC 25-1-9.5 IS ADDED TO READ AS FOLLOWS:

**675 IAC 25-1-9.5 Section 503.6.9.1; Category I appliances**

**Authority:** IC 22-13-2-2; IC 22-13-2-13

**Affected:** IC 22-12; IC 22-13; IC 22-14; IC 22-15; IC 36-7

**Sec. 9.5. In Section 503.6.9.1, Category I appliances, in Exception number 2, in the fifth line, delete “outlets” and insert “outlet” and, in the sixth line, delete “smallest” and insert “smaller”.** (*Fire Prevention and Building Safety Commission; 675 IAC 25-1-9.5; filed Aug 29, 2005, 9:45 a.m.: 29 IR 12*)

SECTION 7. 675 IAC 25-1-9.7 IS ADDED TO READ AS FOLLOWS:

**675 IAC 25-1-9.7 Section 503.7.5; roof penetrations**

**Authority:** IC 22-13-2-2; IC 22-13-2-13

**Affected:** IC 22-12; IC 22-13; IC 22-14; IC 22-15; IC 36-7

**Sec. 9.7. In the third line of Section 503.7.5, Roof penetrations, delete “jacket” and insert “jack”.** (*Fire Prevention and Building Safety Commission; 675 IAC 25-1-9.7; filed Aug 29, 2005, 9:45 a.m.: 29 IR 12*)

SECTION 8. 675 IAC 25-1-9.9 IS ADDED TO READ AS FOLLOWS:

**675 IAC 25-1-9.9 Section 504.2.9; chimney and vent locations**

**Authority:** IC 22-13-2-2; IC 22-13-2-13

**Affected:** IC 22-12; IC 22-13; IC 22-14; IC 22-15; IC 36-7

**Sec. 9.9. In Section 504.2.9, Chimney and vent locations, change, in item 4, the second line to read: given by Table 504.2(3).** (*Fire Prevention and Building Safety Commission; 675 IAC 25-1-9.9; filed Aug 29, 2005, 9:45 a.m.: 29 IR 12*)

*LSA Document #04-218(F)*

*Notice of Intent Published: September 1, 2004; 27 IR 4047*

*Proposed Rule Published: January 1, 2005; 28 IR 1309*

*Hearing Held: March 17, 2005 AND May 4, 2005*

*Approved by Attorney General: August 23, 2005*

*Approved by Governor: August 29, 2005*

*Filed with Secretary of State: August 29, 2005, 9:45 a.m.*

*IC 4-22-7-5(c) Notice from Secretary of State Regarding Documents Incorporated by Reference: None Received by Publisher*